i i	Туре	L #	Hits	Search Text	DBs
1	IS&R	L1	1332	(606/61).CCLS.	USPAT
2	BRS	L2	218	ll and (bushing or washer)	USPAT
3	BRS	L3	o	l2 and elastic\$2 near (pin or screw)	USPAT
4	BRS	L4	1	<pre>12 and spring near (pin or screw)</pre>	USPAT
5	BRS	L5	12	12 and screw near lock	USPAT
6	BRS	L6	10	("5470333" "6176861").PN. OR ("6235033").URPN.	US- PGPUB ; USPAT ; USOCR
7	BRS	L 7	363	plate and washer and bushing and screw near lock	US- PGPUB ; USPAT ; USOCR
8	BRS	L8	6	17 and (elastic or spring)near loaded near (screw or pin)	US- PGPUB ; USPAT ; USOCR
9	BRS	L9	7	("5489210" "5569251" "5713900" "5843082" "6036693" "6168597" "6235033").PN. OR ("6613053").URPN.	US- PGPUB ; USPAT ; USOCR

7				US- PGPUB
10	BRS	11.1()	screw and back near out prevent\$3	; USPAT
				; USOCR

,	Time	Stamp	Comments	Error Definition	Err
1	2005/ 15:31	01/26			
2	 	01/26			
3	2005/ 15:33	01/26			_
4	2005/ 15:33	01/26			
5	2005/ 15:35	01/26			
6	2005/ 15:38	01/26			
7	2005/ 15:39	01/26			
8	2005/ 15:39	01/26		·	
9	2005/ 15:45	01/26			
10	2005/ 15:45	01/26		·	

	Туре	L #	Hits	Search Text	DBs
11	BRS	L11	34	screw and back near out near prevent\$3	US- PGPUB ; USPAT ; USOCR
12	BRS	L12	23	thramann.in.	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB
13	BRS	L13	13956	(fulton or hildebrand or powell).in.	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB

	Time	Stamp	Comments	Error Definition	Err
11	2005/ 15:49	′01/26 Э			
12	2005/ 15:53	/01/26 3			
13	2005/ 15:53	/01/26 3			

•	Туре	L #	Hits	Search Text	DBs
14	BRS	L14	121 X I	l13 and (bushing or washer)	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB
15	BRS	L15	6	ll4 and ((back near out near prevent\$4) or (screw near lock))	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB

	Time	Stamp	Comments	Error Definition	Err
	2005/ 15:54	'01/26 !			
15	2005/ 15:55	/01/26 5			